

EC DECLARATION OF CONFORMITY

Manufacturer or his authorised representative established in European Union:

Voženílek pracovní ochranné pomůcky s.r.o.
Tržní ulice 1
750 02 Přerov I - Město
Czech Republic
IČ: 258 52 141

declares that the Personal Protective Equipment (PPE) hereafter as:

SAM - protective gloves - category II
(cowsplit leather, length 35 cm, protected seams, cotton lining)

are in conformity with the provisions of Czech Government no. 21/2003 c. l. which are taken over from the provisions of Council Directive 89/686/EEC about the laws of the Member States relating to personal protective equipment, as amended by Directives 93/68/EHS, 93/95/EHS and European Council Directive 95/98/ES

are identical to the model of the PPE unit which is the subject of the EC type-examination certificate no. 11 1006 T/NB (dated 25th November 2011) issued by the notified body no. 1023 (ITC a. s. Zlín, Czech Republic).

Testing a model of the PPE demonstrated conformity with the requirements of its properties with National Standards transposing the harmonised European Standard Numbers:

ČSN EN 420:2004+A1 2010 : Protective gloves - General requirements and test methods.

ČSN EN 388:2004 : Protective gloves against mechanical risks. (3-3-4-3)

ČSN EN 407:2005 : Protective gloves against thermal risks. (4-1-3-x-4-x)

ČSN EN 12477:2002/A1:2005 : Protective gloves for welders.

Signed in Přerov
Date: 13th February 2012


Mgr. Tomáš Voženílek
Managing director

Information for users

Gloves SAM are five finger welding gloves, made of split cowhide lined with non-woven fabric cotton. Size 10. Gloves are marked in conformity with the European standards EN 420V:2003, EN 388:2003, EN 12477:2003 by the mark of supplier, the type number, the year of the production and the pictograms of the protective determination.

Use

Gloves are intended for protection of hands against mechanical hazard and for welding. Grasp ability of the gloves is very good. Protective features relate to a whole glove. Don't use crusted gloves or gloves damaged in some other way.

Rates of protection according to EN 388

Abrasive resistance	3
Cut resistance	3
Resistance against further ripping	4
Perforation resistance	3

Rate of protection according to EN 407

Fire resistance	4
Immunity to contact heat	1
Immunity to conventional heat	3
Immunity to heat of radiation	X
Immunity to slight splashing	4
Immunity to heavy splashing	X

Gloves are of A rate.

Instructions for maintenance of protective gloves

Don't expose the gloves to heat of radiation, organic solvents and their fumes, lubricants, grease, mineral oils, caustics and water. Clear away dirt with a brush and store the gloves in a room temperature. You cannot wash or dry-clean the gloves.



Prodejní sklad:
Tržní 1, 750 02 Píerov Czech Republic
Tel: 581 250 061, 581 250 076
Fax:581 203 626

Storage of gloves

Store the gloves in a dry place with the range of 0°C + 30°C without direct solar radiation.

Certificate was issued by a notified subject No 1023 (Institute for Testing and Certification Inc., 299 T. Bati, Zlín, Czech Republic).